

**DRINKING WATER SOURCE PROTECTION**  
**Assessment Report Map # 9**  
**Physiography**

This publication was produced by:  
 Lakehead Region Conservation Authority (LRCA)  
 130 Conservation Road  
 Thunder Bay, ON, P7B 6T8  
 807-344-5857


© 2011 Lakehead Region Conservation Authority. All Rights Reserved.

Base data supplied, under licence, by members of the Ontario Geospatial Data Exchange. Map produced in co-operation with the Province of Ontario.

This map is for illustrative purposes only and is not reliable as a precise indicator of routes, location of features, nor as a guide to navigation.



Surficial Geology		Surficial Line Features		Surficial Point Features	
LANDFORM	DESCRIPTION	DESCRIPTION	DESCRIPTION	DESCRIPTION	DESCRIPTION
Moraine	Abandoned River Channel	Local Dune Area	Glaciolacustrine plain	Small Landslide Scar	Talus
Esker	Abandoned Shoreline	Talus	Alluvial	Municipal Residential Drinking Water System	Major End Moraine
Kame	Escarpment	Other Linear Ice-Flow Features	Slope failure	Large	Drumlin
Outwash plain	Esker	Steep-Walled Valleys	Talus pile	Small	Other Linear Ice-Flow Features
Raised beach	Major End Moraine		Slopewash and debris creep	Boundaries	Other Linear Ice-Flow Features
Glaciolacustrine delta	Drumlin		Sand dunes	Lakehead Source Protection Area	Other Linear Ice-Flow Features
	Other Linear Ice-Flow Features		Organics	LRCA Jurisdiction Boundary	Other Linear Ice-Flow Features
	Steep-Walled Valleys		Bedrock	Highway	Other Linear Ice-Flow Features



Prepared By: Roman Augustyn  
 Date: March 2011  
 Projection Information:  
 Name: NAD 1983 UTM Zone 16N  
 Projection: Transverse Mercator  
 Datum: North American 1983  
 Lakehead Region Conservation Authority

